



(Registered under the Societies Registration Act XXI of 1860) Registration No. 470/2006

Dated: 26<sup>th</sup> February, 2018

## Classroom renovation

289,633

14,482

275,151

22<sup>nd</sup> November, 2017

15<sup>th</sup> February, 2018

### Work Description:

1. Removing existing windows and replacing them with two double windows.
2. Complete floor plastering of **five** classrooms and passage plastering of 73.8 feet (L) x 5 feet (B) = 369 sq.ft.
3. Wall protection slope on a side of a building.
4. Window panels for 8 new windows.
5. Repaint of all the 8 class rooms excluding ceilings.
6. Replacing some broken window panes.

1. The extension of windows is based on situation the school experienced. The classrooms with only two windows on each side made it suffocating in a long period of hot summer months. With the scarce electricity, the classrooms are filled with sweaty and hot body smell resulting in children coming out of the classroom constantly. They are seen seeking for an excuse merely to come out of the class. So analyzing this problem the school made a decision that these windows need to get extended so that more fresh air generates in the classrooms resulting in creating an inviting ambience.
2. We could also make wall protection slope on a side of a 1<sup>st</sup> block building. Without the slope, the constant rain water was penetrating into the earth resulting in slow separation of earth and the foundation of the building
3. Floor plastering: over the period of time the floors of the classrooms have had pit holes making classrooms look untidy. So the floors of all the 8 classrooms were completely re-plastered.
4. These classrooms' interior walls and exterior walls were repainted to give a final finishing touch.
5. Window panels for 8 new windows: Although we had ten new windows in total but we have made only 8 window panels because one of the classroom's old windows don't have panels so to match the old windows we have exempted making one for this class room.
6. Some of the window panes were lying broken since long time so we have fixed these panes.

Session Road, Dharamsala-176215 District: Kangra (H.P.) INDIA

**Phone:** 01892-228877 / 226877 **E-mail:** stss1999@gmail.com **Website:** <http://www.sambhota.org>



(Registered under the Societies Registration Act XXI of 1860) Registration No. 470/2006

- Word of gratitude:**

**Phone:** 01892-228877 / 226877 **E-mail:** stss1999@gmail.com **Website:** <http://www.sambhota.org>





(Registered under the Societies Registration Act XXI of 1860) Registration No. 470/2006

The image is a 2x2 grid of photographs documenting the demolition of a building. The top-left photo shows the interior of a room with several windows and debris on the floor. The top-right photo shows the exterior of a building with a blue base and white upper section, with a large opening in the wall. The bottom-left photo shows a person in a red shirt working on a wooden structure outside the building. The bottom-right photo shows a person in a red shirt working on a wooden structure outside the building, with a large opening in the wall.

**Phone:** 01892-228877 / 226877 **E-mail:** stss1999@gmail.com **Website:** <http://www.sambhota.org>





༡ བོད་ཁྱེད་ཀྱི་སྒྲིག་ཁྲིམས་ལྟེ་གཞི་གཞི་ལྟེ་གཞི་

**Sambhota Tibetan Schools Society**

(Registered under the Societies Registration Act XXI of 1860) Registration No. 470/2006







འབྲེལ་ཤིང་གྲོལ་བྱེད་ལྷན་ཁག་གི་ལྷན་ཁག་

**Sambhota Tibetan Schools Society**

(Registered under the Societies Registration Act XXI of 1860) Registration No. 470/2006







(Registered under the Societies Registration Act XXI of 1860) Registration No. 470/2006

